



2061/037

1st June 2018

-Translation-

Subject: Temporary problem with transmission line system
To: President of the Stock Exchange of Thailand

Banpu Power Public Company Limited ('the company') would like to inform the Stock Exchange of Thailand that the company had been notified by Hongsa Power Company Limited that at 13:06 hrs. there was lightning on 500 kV transmission line located 14 km from Hongsa Power plant. The transmission and substation protection system activated, therefore transmission system was temporarily disconnected from the power plant. The system resumed normal operation at 14:47 hrs.

Please be informed accordingly and kindly disseminate the herein information to investors.

Sincerely Yours,

-signature-

(Mr. Sutee Sukruan)
Chief Executive Officer